

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
Apple	iPhone	unknown	✓	✓	✓	✓
Apple	iPhone 3G	unknown	✓	✓	✓	✓
Apple	iPhone 3G	unknown	✓	✓	✓	✓
Asus	M530w	V4.1.10_EU1	✓	✓	✓	✓
Asus	P320	unknown	✓	✓	✓	✓
Asus	P750	unknown	✓	✓	✓	✓
BenQSiemens	EF81	unknown	✓	✓	✓	✓
BenQSiemens	S68	38	✓	✓	✓	✓
BenQSiemens	A58	unknown	✓	✓	✓	✓
BenQSiemens	C81	unknown	✓	✓	✓	✓
BenQSiemens	CF61	unknown	✓	✓	✓	✓
BenQSiemens	CL71	unknown	✓	✓	✓	✓
BenQSiemens	E71	unknown	✓	✓	✓	✓
BenQSiemens	E81	unknown	✓	✓	✓	✓
BenQSiemens	EF51	unknown	✓	✓	✓	✓
BenQSiemens	EF61	unknown	✓	✓	✓	✓
BenQSiemens	EF71	unknown	✓	✓	✓	✓
BenQSiemens	EF81	unknown	✓	✓	✓	✓
BenQSiemens	EF91	unknown	✓	✓	✓	✓
BenQSiemens	EL71	unknown	✓	✓	✓	✓
BenQSiemens	M81	unknown	✓	✓	✓	✓
BenQSiemens	P51	unknown	✓	✓	✓	✓
BenQSiemens	S81	unknown	✓	✓	✓	✓
BenQSiemens	S88	unknown	✓	✓	✓	✓
BenQSiemens	SL80	unknown	✓	✓	✓	✓
BenQSiemens	SL91	unknown	✓	✓	✓	✓
BlackBerry	7100g	unknown	✓	✓	✓	✓
BlackBerry	7100r	unknown	✓	✓	✓	✓
BlackBerry	7100t	unknown	✓	✓	✓	✓
BlackBerry	7100v	unknown	✓	✓	✓	✓
BlackBerry	7100x	unknown	✓	✓	✓	✓
BlackBerry	7130c	unknown	✓	✓	✓	✓
BlackBerry	7130e	unknown	✓	✓	✓	✓
BlackBerry	7130g	unknown	✓	✓	✓	✓
BlackBerry	7230e	unknown	✓	✓	✓	✓
BlackBerry	7250	unknown	✓	✓	✓	✓
BlackBerry	7290	unknown	✓	✓	✓	✓
BlackBerry	7290e	unknown	✓	✓	✓	✓
BlackBerry	7520	unknown	✓	✓	✓	✓
BlackBerry	8100	V4.2.051	✓	✓	✓	✓
BlackBerry	8120	v4.3.0.14 Platform 2.6.0.11	✓	✓	✓	✓
BlackBerry	8130	v4.3	✓	✓	✓	✓
BlackBerry	8300	unknown	✓	✓	✓	✓
BlackBerry	8310	unknown	✓	✓	✓	✓
BlackBerry	8700c	unknown	✓	✓	✓	✓
BlackBerry	8700f	unknown	✓	✓	✓	✓
BlackBerry	8700g	unknown	✓	✓	✓	✓
BlackBerry	8700r	unknown	✓	✓	✓	✓
BlackBerry	8707v	unknown	✓	✓	✓	✓
BlackBerry	8800	V4.2.173	✓	✓	✓	✓
BlackBerry	8820	v4.2.2.160 / t724	✓	✓	✓	✓
BlackBerry	8830	v4.2.2.176 (Platform 3.0.0.79)	✓	✓	✓	✓
BlackBerry	8120 Pearl	unknown	✓	✓	✓	✓
BlackBerry	8130 Pearl	unknown	✓	✓	✓	✓
HP	iPAQ hw6910	1.47.00 GER	✓	✓	✓	✓
HP	iPAQ 514	CE BS 5.2.1237	✓	✓	✓	✓
HTC	Dash	5.2.1236	✓	✓	✓	✓
HTC	Mogul PPC6800	5.2.1238	✓	✓	✓	✓
HTC	P3300	1.14.407.1 GER	✓	✓	✓	✓
HTC	P3470 Pharos	unknown	✓	✓	✓	✓
HTC	P3600	1.16.407.2	✓	✓	✓	✓
HTC	P4550	ROM-Version: 1.56.407 ROM-Datum: 09.05.2007	✓	✓	✓	✓

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
HTC	P6300	1.1.7	✓	✓	✓	✓
HTC	S710	1.16.407.1	✓	✓	✓	✓
HTC	Touch	1.15.162.1.GER	✓	✓	✓	✓
HTC	Touch Cruise	1.25	✓	✓	✓	✓
HTC	Touch Pro	unknown	✓	✓	✓	✓
HTC	Dash	unknown	✓	✓	✓	✓
HTC	P3600	unknown	✓	✓	✓	✓
HTC	Touch	unknown	✓	✓	✓	✓
HTC	P4350	1.8.407.1.GER	✓	✓	✓	✓
KDDI - HITACHI	W62H	unknown	✓	✓	✓	✓
KDDI - SANYO	W63SA	unknown	✓	✓	✓	✓
KDDI - SANYO	W64SA	unknown	✓	✓	✓	✓
KDDI - SHARP	W62SH	unknown	✓	✓	✓	✓
KDDI - Toshiba	Sportio	unknown	✓	✓	✓	✓
LGE	CE110	unknown	✓	✓	✗	✗
LGE	CU515	unknown	✓	✓	✓	✓
LGE	KE850Prada	T616	✓	✓	✓	✓
LGE	KF700	V10d	✗	✗	✗	✗
LGE	KF600	unknown	✓	✓	✓	✓
LGE	KF750	unknown	✓	✓	✓	✓
LGE	KS360	unknown	✓	✓	✓	✓
LGE	KS20	V10b	✓	✓	✓	✓
LGE	KU800	v10_b	✓	✓	✓	✓
LGE	KU970	unknown	✓	✓	✓	✓
LGE	KU990	unknown	✓	✓	✓	✓
LGE	LX150	unknown	✓	✓	✓	✓
LGE	LX160	LX160V04	✗	✗	✗	✗
LGE	LX600	unknown	✓	✓	✗	✓
LGE	VX 8560	unknown	✓	✓	✓	✓
LGE	VX5400	VX540V01	✓	✓	✓	✓
LGE	VX8300	unknown	✓	✓	✓	✓
LGE	VX8350	unknown	✓	✓	✓	✓
LGE	VX8500 Chocolate	unknown	✓	✓	✓	✓
LGE	VX8610	unknown	✓	✓	✓	✓
Microsoft	T-Mobile SDA	V4.21.1088	✓	✓	✓	✓
Motorola	A1200	unknown	✓	✓	✓	✓
Motorola	E1	unknown	✓	✓	✓	✓
Motorola	E815	unknown	✓	✓	✓	✓
Motorola	E1000	unknown	✓	✓	✓	✓
Motorola	E550	unknown	✓	✓	✓	✓
Motorola	Mototorla - I580	F55Cv00.25	✓	✓	✗	✗
Motorola	I880	F56Ev00.29	✓	✓	✗	✗
Motorola	K1	G08.22..07R	✓	✓	✓	✓
Motorola	K1m KRZR	unknown	✓	✓	✓	✓
Motorola	K3	R261171LD_U_99.13.11R	✓	✓	✓	✓
Motorola	L6	R3511 G DA 53	✓	✓	✓	✓
Motorola	L7	R4513 G08.B7.DA	✓	✓	✓	✓
Motorola	MotQ9c	unknown	✓	✓	✓	✓
Motorola	MotW755	unknown	✓	✓	✓	✓
Motorola	Q9	R3511 G DA 53	✓	✓	✓	✓
Motorola	Q9m	unknown	✓	✓	✓	✓
Motorola	U6 PBEL	unknown	✓	✓	✓	✓
Motorola	U9	unknown	✓	✓	✓	✓
Motorola	V3	R374 G OE 40.79R	✓	✓	✓	✓
Motorola	V3c	unknown	✓	✓	✓	✓
Motorola	V3i	unknown	✓	✓	✓	✓
Motorola	V3-US	unknown	✓	✓	✓	✓
Motorola	V360	unknown	✓	✓	✓	✓
Motorola	V3x	unknown	✓	✓	✓	✓
Motorola	V3XX	R26111LD_U_96.6	✓	✓	✓	✓
Motorola	V500	unknown	✓	✓	✓	✓
Motorola	V525M	unknown	✓	✓	✓	✓
Motorola	V600	unknown	✓	✓	✓	✓
Motorola	V600i	unknown	✓	✓	✓	✓
Motorola	V635	unknown	✓	✓	✓	✓
Motorola	V8	R601_G_80.42	✓	✓	✓	✓
Motorola	V9	R263313_U_A0.01.10R31	✓	✓	✓	✓
Motorola	V9m	TRPLT2_02.68.00R	✓	✓	✓	✓
Motorola	W510	unknown	✓	✓	✓	✓
Motorola	Z3	R4527 G 08.01.02R	✓	✓	✓	✓
Motorola	Z6	R60_G_80.32.0FR	✓	✓	✓	✓
Motorola	Z6 VZW	JACQUE_01.30.11P	✓	✓	✓	✓
Motorola	Z6c	unknown	✓	✓	✓	✓
Motorola	Z8	ESPOO_U_46.03.E3G	✗	✗	✗	✗
Nokia	3109	V 05.30	✓	✓	✓	✓

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
Nokia	5500	V03.18	✓	✓	✓	✓
Nokia	3250	unknown	✓	✓	✓	✓
Nokia	3109c	V05.	✓	✓	✓	✓
Nokia	3110c	V05.	✓	✓	✓	✓
Nokia	3600slide	unknown	✓	✓	✓	✓
Nokia	3650	unknown	✓	✓	✓	✓
Nokia	5200	V04.71	✓	✓	✓	✓
Nokia	5300	V05.00	✓	✓	✓	✓
Nokia	5310	V03	✓	✓	✓	✓
Nokia	5500 Sport	unknown	✓	✓	✓	✓
Nokia	5610	unknown	✓	✓	✓	✓
Nokia	5700	V03	✓	✓	✓	✓
Nokia	6021	V04.10	✓	✓	✓	✓
Nokia	6103	V4.90	✓	✓	✓	✓
Nokia	6110	V03.58	✓	✓	✓	✓
Nokia	6111	V03.58	✓	✓	✓	✓
Nokia	6125	unknown	✓	✓	✓	✓
Nokia	6131	unknown	✓	✓	✓	✓
Nokia	6151	V03.56	✓	✓	✓	✓
Nokia	6220 classic	unknown	✓	✓	✓	✓
Nokia	6230b	unknown	✓	✓	✓	✓
Nokia	6230i	V3.40	✓	✓	✓	✓
Nokia	6233	V03.70	✓	✓	✓	✓
Nokia	6234	V03.05	✓	✓	✓	✓
Nokia	6270	unknown	✓	✓	✓	✓
Nokia	6280	unknown	✓	✓	✓	✓
Nokia	6288	V06	✓	✓	✓	✓
Nokia	6300	unknown	✓	✓	✓	✓
Nokia	6300i	unknown	✓	✓	✓	✓
Nokia	6310	unknown	✓	✓	✓	✓
Nokia	6310i	V5.22	✓	✓	✓	✓
Nokia	6500 classic	V 03.21	✓	✓	✓	✓
Nokia	6500 slider	V06	✓	✓	✓	✓
Nokia	6555b	V03.31-RM289	✓	✓	✓	✓
Nokia	6600slide	unknown	✓	✓	✓	✓
Nokia	6650	unknown	✓	✓	✓	✓
Nokia	6630	unknown	✓	✓	✓	✓
Nokia	6682	unknown	✓	✓	✓	✓
Nokia	6680	unknown	✓	✓	✓	✓
Nokia	6820A	V05.88	✓	✓	✓	✓
Nokia	6820b	unknown	✓	✓	✓	✓
Nokia	6822a	unknown	✓	✓	✓	✓
Nokia	6822b	unknown	✓	✓	✓	✓
Nokia	7370	unknown	✓	✓	✓	✓
Nokia	6810	unknown	✓	✓	✓	✓
Nokia	8910i	unknown	✓	✓	✓	✓
Nokia	3230	unknown	✓	✓	✓	✓
Nokia	7390	V04.51	✓	✓	✓	✓
Nokia	7500 Prism	V03	✓	✓	✓	✓
Nokia	7610	unknown	✓	✓	✓	✓
Nokia	7600	unknown	✓	✓	✓	✓
Nokia	7610b	unknown	✓	✓	✓	✓
Nokia	8600 Luna	V 03.52	✓	✓	✓	✓
Nokia	8800	unknown	✓	✓	✓	✓
Nokia	8800 Arte	V06	✓	✓	✓	✓
Nokia	8801	unknown	✓	✓	✓	✓
Nokia	9300b	unknown	✓	✓	✓	✓
Nokia	9300i	V05.50	✓	✓	✓	✓
Nokia	9500	unknown	✓	✓	✓	✓
Nokia	9500b	unknown	✓	✓	✓	✓
Nokia	E50	V06.27.1.0	✓	✓	✓	✓
Nokia	E51	V100.	✓	✓	✓	✓
Nokia	E60	unknown	✓	✓	✓	✓
Nokia	E61	n.a	✓	✓	✓	✓
Nokia	E61i	1.0633.22.05	✓	✓	✓	✓
Nokia	E65	1.0633.18.01	✓	✓	✓	✓
Nokia	E70	2.0618.07.10	✓	✓	✓	✓
Nokia	E90	V07.29.03	✗	✗	✗	✗
Nokia	N70	unknown	✓	✓	✓	✓
Nokia	N71	unknown	✓	✓	✓	✓
Nokia	N73	V05.02	✓	✓	✓	✓
Nokia	N76	V10.0.035	✓	✓	✓	✓
Nokia	N78	unknown	✓	✓	✓	✓
Nokia	N80	unknown	✓	✓	✓	✓
Nokia	N80	unknown	✓	✓	✓	✓

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
Nokia	N81	V1	✓	✓	✓	✓
Nokia	N93	unknown	✓	✓	✓	✓
Nokia	N93i	V10.0.025	✓	✓	✓	✓
Nokia	N95	V12.0.013	✓	✓	✓	✓
Nokia	N95 8G	unknown	✓	✓	✓	✓
NTT - Fujitsu	F1100	unknown	✓	✓	✓	✓
NTT - Nokia	NM706i	unknown	✓	✓	✓	✓
NTT - Panasonic	P905i	unknown	✓	✓	✓	✓
NTT - Panasonic	P905iTV	unknown	✓	✓	✓	✓
NTT - Panasonic	P906i	unknown	✓	✓	✓	✓
NTT - SHARP	SH906i	unknown	✓	✓	✓	✓
NTT - SHARP	SH906iTV	unknown	✓	✓	✓	✓
Palm	Centro	unknown	✓	✓	✓	✓
Palm	Treo 500v	unknown	✓	✓	✓	✓
Palm	Treo 700wx	unknown	✓	✓	✓	✓
Palm	Treo 750	TREO750-1.16-RWG	✓	✓	✓	✓
Palm	Treo 750v	unknown	✓	✓	✓	✓
Palm	Treo 755p	unknown	✓	✓	✓	✓
Palm	Treo800W	unknown	✓	✓	✓	✓
Pantech - Breeze	C520	unknown	✓	✓	✓	✓
Philips	768	unknown	✓	✓	✓	✓
Sagem	my401x	unknown	✓	✓	✓	✓
Sagem	my511x	E	✓	✓	✓	✓
Sagem	my700x	unknown	✓	✓	✓	✓
Samsung	D600	unknown	✓	✓	✓	✓
Samsung	X830	unknown	✓	✓	✓	✓
Samsung	D900i	T659/?	✓	✓	✓	✓
Samsung	I300	I300XXFB2	✓	✓	✓	✓
Samsung	I600	5.1.525.15363	✓	✓	✓	✓
Samsung	U700	U700AKGF1	✓	✓	✓	✓
Samsung	X820	X820XXFF2	✓	✓	✓	✓
Samsung	Samsang - SGH-D900i	unknown	✓	✓	✓	✓
Samsung	Samsang - SGH-I300	unknown	✓	✓	✓	✓
Samsung	Instinct M800	unknown	✓	✓	✓	✓
Samsung	Samsung SGH-F700	unknown	✓	✓	✓	✓
Samsung	SCH-i760	unknown	✓	✓	✓	✓
Samsung	SCH-u470 Juke	unknown	✓	✓	✓	✓
Samsung	SCH-U550	unknown	✓	✓	✓	✓
Samsung	SCH-U940	unknown	✓	✓	✗	✗
Samsung	SGH T439	unknown	✓	✓	✓	✓
Samsung	SGH-D880	unknown	✓	✓	✓	✓
Samsung	SGH-E590	unknown	✓	✓	✓	✓
Samsung	SGH-E740	E740BOGH3	✓	✓	✓	✓
Samsung	SGH-E830	E830XWGD1	✓	✓	✓	✓
Samsung	SGH-F330	unknown	✓	✓	✓	✓
Samsung	SGH-G600	G600XWGH3	✓	✓	✓	✓
Samsung	SGH-G800	unknown	✓	✓	✓	✓
Samsung	SGH-i600	unknown	✓	✓	✓	✓
Samsung	SGH-i780	unknown	✓	✓	✓	✓
Samsung	SGH-J700	unknown	✓	✓	✓	✓
Samsung	SGH-P520 Armani	unknown	✓	✓	✓	✓
Samsung	SGH-T739 Katalyst	unknown	✓	✓	✓	✓
Samsung	SGH-U700	unknown	✓	✓	✓	✓
Samsung	SGH-U900 Soul	unknown	✓	✓	✓	✓
Samsung	SGH-x820	unknown	✓	✓	✓	✓
Samsung	SPH-A900	ES.A900-AB15	✓	✓	✓	✓
Samsung	SPH-M520	ES.M620 AF14	✓	✓	✓	✓
Sanyo	SCP-6650	1.004SP	✓	✓	✓	✓
Sanyo	SCP-8500	1.002SP	✓	✓	✓	✓
Sanyo	Katana II	unknown	✓	✓	✓	✓
Sanyo	KatanaLX	unknown	✓	✓	✓	✓
Sharp	804SH	unknown	✓	✓	✓	✓
Sharp	904SH	unknown	✓	✓	✓	✓
Sharp	905SH	unknown	✓	✓	✓	✓
Siemens	S65	16	✓	✓	✓	✓
Siemens	S66	unknown	✓	✓	✓	✓
Siemens	SX1	unknown	✓	✓	✓	✓
Siemens	SX66	unknown	✓	✓	✓	✓
Siemens	SXG75	unknown	✓	✓	✓	✓
Siemens	CX75	unknown	✓	✓	✓	✓
Siemens	M75	unknown	✓	✓	✓	✓
Siemens	S55	unknown	✓	✓	✓	✓
Siemens	S75	24	✓	✓	✓	✓
Siemens	SK65	46	✓	✓	✓	✓
Siemens	SL75	unknown	✓	✓	✓	✓

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
Siemens	SP65	50	✓	✓	✓	✓
Siemens	AC45	unknown	✓	✓	✓	✓
Siemens	AC75	unknown	✓	✓	✓	✓
SoftBank - Panasonic	920P	unknown	✓	✓	✓	✓
SoftBank - Samsung	920SC	unknown	✓	✓	✓	✓
SoftBank - SHARP	923SH	unknown	✓	✓	✓	✓
Sony-Ericsson	D750	unknown	✓	✓	✓	✓
Sony-Ericsson	D750i	unknown	✓	✓	✓	✓
Sony-Ericsson	K310	unknown	✓	✓	✓	✓
Sony-Ericsson	K510a	unknown	✓	✓	✓	✓
Sony-Ericsson	K510c	unknown	✓	✓	✓	✓
Sony-Ericsson	K510i	R4EA031	✓	✓	✓	✓
Sony-Ericsson	K550	R1JD001	✓	✓	✓	✓
Sony-Ericsson	K600i	unknown	✓	✓	✓	✓
Sony-Ericsson	K608	unknown	✓	✓	✓	✓
Sony-Ericsson	C702	unknown	✓	✓	✓	✓
Sony-Ericsson	C902	unknown	✓	✓	✓	✓
Sony-Ericsson	G900	unknown	✓	✓	✓	✓
Sony-Ericsson	K610i	R1CB001	✓	✓	✓	✓
Sony-Ericsson	K618	unknown	✓	✓	✓	✓
Sony-Ericsson	K700i	R2AE033	✓	✓	✓	✓
Sony-Ericsson	K750c	unknown	✓	✓	✓	✓
Sony-Ericsson	K750i	R1A044	✓	✓	✓	✓
Sony-Ericsson	K790	unknown	✓	✓	✓	✓
Sony-Ericsson	K800c	unknown	✓	✓	✓	✓
Sony-Ericsson	K800i	R1JC002	✓	✓	✓	✓
Sony-Ericsson	K810i	R1KG001	✓	✓	✓	✓
Sony-Ericsson	K850i	R1CA029	✓	✓	✓	✓
Sony-Ericsson	M600	unknown	✓	✓	✓	✓
Sony-Ericsson	M600i	R4A002	✓	✓	✓	✓
Sony-Ericsson	M600c	unknown	✓	✓	✓	✓
Sony-Ericsson	M608	unknown	✓	✓	✓	✓
Sony-Ericsson	P1i	R9G007	✓	✓	✓	✓
Sony-Ericsson	P800	unknown	✓	✓	✓	✓
Sony-Ericsson	P910a	unknown	✓	✓	✓	✓
Sony-Ericsson	P910c	unknown	✓	✓	✓	✓
Sony-Ericsson	P910i	unknown	✓	✓	✓	✓
Sony-Ericsson	P990c	unknown	✓	✓	✓	✓
Sony-Ericsson	P990i	R7A001	✓	✓	✓	✓
Sony-Ericsson	S600c	unknown	✓	✓	✓	✓
Sony-Ericsson	S600i	unknown	✓	✓	✓	✓
Sony-Ericsson	S700a	unknown	✓	✓	✓	✓
Sony-Ericsson	S700c	unknown	✓	✓	✓	✓
Sony-Ericsson	S700i	unknown	✓	✓	✓	✓
Sony-Ericsson	S710a	unknown	✓	✓	✓	✓
Sony-Ericsson	T608	unknown	✓	✓	✓	✓
Sony-Ericsson	T610	unknown	✓	✓	✓	✓
Sony-Ericsson	T616	unknown	✓	✓	✓	✓
Sony-Ericsson	T618	unknown	✓	✓	✓	✓
Sony-Ericsson	T628	unknown	✓	✓	✓	✓
Sony-Ericsson	T630	unknown	✓	✓	✓	✓
Sony-Ericsson	T637	unknown	✓	✓	✓	✓
Sony-Ericsson	T68	unknown	✓	✓	✓	✓
Sony-Ericsson	T68i	unknown	✓	✓	✓	✓
Sony-Ericsson	T68m	unknown	✓	✓	✓	✓
Sony-Ericsson	V600	unknown	✓	✓	✓	✓
Sony-Ericsson	V630	unknown	✓	✓	✓	✓
Sony-Ericsson	V630i	unknown	✓	✓	✓	✓
Sony-Ericsson	V800i	unknown	✓	✓	✓	✓
Sony-Ericsson	W300	unknown	✓	✓	✓	✓
Sony-Ericsson	W550c	unknown	✓	✓	✓	✓
Sony-Ericsson	W550i	unknown	✓	✓	✓	✓
Sony-Ericsson	W600	unknown	✓	✓	✓	✓
Sony-Ericsson	W600a	unknown	✓	✓	✓	✓
Sony-Ericsson	W600i	unknown	✓	✓	✓	✓
Sony-Ericsson	W610i	R1KG001	✓	✓	✓	✓
Sony-Ericsson	W700	unknown	✓	✓	✓	✓
Sony-Ericsson	W710	unknown	✓	✓	✓	✓
Sony-Ericsson	W800c	unknown	✓	✓	✓	✓
Sony-Ericsson	W800i	R1AA008	✓	✓	✓	✓
Sony-Ericsson	W810c	unknown	✓	✓	✓	✓
Sony-Ericsson	W810i	R4CE012	✓	✓	✓	✓
Sony-Ericsson	W850i	unknown	✓	✓	✓	✓
Sony-Ericsson	W880i	R1JC002	✓	✓	✓	✓
Sony-Ericsson	W890i	unknown	✓	✓	✓	✓

Fabrikant	Getest model	Firmware versie van het geteste model	Verbinding tussen auto en telefoon	Bellen	Accepteren en beëindigen van gesprek	Weigeren van een gesprek
Sony-Ericsson	W900c	unknown	✓	✓	✓	✓
Sony-Ericsson	W900i	unknown	✓	✓	✓	✓
Sony-Ericsson	W910i	R1CA029	✓	✓	✓	✓
Sony-Ericsson	W950i	R9C001	✓	✓	✓	✓
Sony-Ericsson	W960i	BT: CXC162143R1D	✓	✓	✓	✓
Sony-Ericsson	Z520a	unknown	✓	✓	✓	✓
Sony-Ericsson	Z520i	unknown	✓	✓	✓	✓
Sony-Ericsson	Z525	unknown	✓	✓	✓	✓
Sony-Ericsson	Z530i	unknown	✓	✓	✓	✓
Sony-Ericsson	Z550	unknown	✓	✓	✓	✓
Sony-Ericsson	Z600	unknown	✓	✓	✓	✓
Sony-Ericsson	Z608	unknown	✓	✓	✓	✓
Sony-Ericsson	Z710i	R1ED001	✓	✓	✓	✓
Sony-Ericsson	Z800i	unknown	✓	✓	✓	✓
Sony-Ericsson	Z610i	unknown	✓	✓	✓	✓